### OPLYSNINGER OM SIKKER BRUG AF SVHC

REACH-ARTIKEL 33 OPLYSNINGER OM STOFFER, DER ANSES FOR AT VÆRE SÆRLIGT PROBLEMATISKE

#### Kære kunde

REACH-forordningen (forordning EF 1907/2006) artikel 33, stk. 1 har til formål at give kunderne af leverede produkter mulighed for at træffe relevante risikostyringsforanstaltninger, der måtte opstå som følge af forekomsten i artikler af stoffer, der anses for at være særligt problematiske (SVHC'er), som er opført på den nuværende kandidatliste til godkendelse, for at sikre deres sikre brug.

FORD støtter de underliggende mål for REACH generelt og artikel 33, stk. 1, specifikt, hvilket er i overensstemmelse med vores egen forpligtelse til at fremme ansvarlig fremstilling, håndtering og brug af vores produkter.

#### Identifikation af SVHC'er

Så vidt vi ved, baseret på oplysninger fra vores forsyningskæde og vores egne produktdata, er de SVHC'er, der findes i komponentartikler på mere end 0,1 % w/w, dem, der er vist på den relevante "SVHC-liste" for det/den specifikke køretøj/del.

#### Specifikke sikkerhedsoplysninger for artikler, der indeholder SVHC'er

Hvis det er relevant, tilføjes specifikke sikkerhedsoplysninger for artikler, der indeholder SVHC'er, til den relevante "SVHC-liste" for det/den specifikke køretøj/del.

#### Generelle sikkerhedsoplysninger for artikler

Hvert FORD-køretøj er forsynet med en manual, som indeholder oplysninger om sikker brug til ejere/operatører af køretøjet. FORD-oplysninger om reparation og eftersyn af køretøjer og originale dele indeholder også oplysninger om sikker brug til servicepersonale.

Der hvor de er til stede i dele af dette køretøj, er SVHC'erne, der er vist på den relevante "SVHC-liste" for det/den specifikke køretøj/del, indarbejdet på en sådan måde, at potentiel eksponering for kunderne er minimeret, og fare for mennesker eller miljøet kan udelukkes som så længe køretøjet og dets dele anvendes efter hensigten, og reparationer, eftersyn og vedligeholdelse udføres efter tekniske instruktioner til disse aktiviteter og god praksis i branchen.

Et udrangeret køretøj må kun bortskaffes lovligt i EU på en autoriseret behandlingsfacilitet (ATF). Køretøjsdelene skal bortskaffes i overensstemmelse med gældende lovgivning og lokal myndighed.

# Model: Mustang MACH E

## SVHC-liste baseret på ECHA-kandidatliste pr. 1. juli 2023

## Specifikke sikkerhedsoplysninger for artikler, der indeholder SVHC'er

Der kræves ingen specifikke sikkerhedsoplysninger - følg generelle sikkerhedsoplysninger for artikler.

Commodity	REACH SVHCs
A/C Compressor	Lead [7439-92-1]
A/C Lines, Receiver Drier and Accumulator	Lead [7439-92-1]
ABS/ESC Module	Lead [7439-92-1]
Accessories	1,2-Dimethoxyethane [110-71-4]
	Lead [7439-92-1]
	Sodium borate, decahydrate [1303-96-4]
Active and Air Suspension	Lead [7439-92-1]
Active Grille Shutter	Lead [7439-92-1]
Adaptive Cruise Control	Lead [7439-92-1]
	Octamethylcyclotetrasiloxane [556-67-2]
Air Bag Module- Pass Side	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Antenna	Lead [7439-92-1]
Appliques (Pillar, Decklid, Roof)	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Lead [7439-92-1]
Audio and Navigation Head Units	Lead [7439-92-1]
Axle	Lead [7439-92-1]
Badges	Lead [7439-92-1]
Battery	Lead [7439-92-1]
Body Side InteriorTrim (Hard Trim)	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Body Structure - Dash and Cowl	Dicyclohexyl-phthalate [84-61-7]
Bodyside, Wheel Arch, Rocker Moldings	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Brake Tubes and Hoses	Lead [7439-92-1]
Brakes - Caliper & Anchor Brkt Assy (Front, Rear)	2-Methylimidazole [693-98-1]
	Lead [7439-92-1]
Bulk Materials (PMT100)	C,C'-azodi(formamide) [123-77-3]
Console Floor/Rear	1,6,7,8,9,14,15,16,17,17,18,18- Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15- diene [13560-89-9]
	Lead [7439-92-1]
	Silicic acid, lead salt [11120-22-2]
Controller Assembly Occupant Restraint (OCS)	TBBA [79-94-7]
Cooling Fans	Lead [7439-92-1]
Cooling Hoses & Bottles	Lead [7439-92-1]
EDS Wiring Assembly & Components	Lead [7439-92-1]
Electrified Drivetrain	Lead [7439-92-1]

Electronic Control Panel and CCH	Silicic acid, lead salt [11120-22-2]
Electronic Modules - Amplifiers	Lead [7439-92-1]
Electronic Modules - Displays	Lead [7439-92-1]
Electronic Modules - Door Zone	Lead [7439-92-1]
Electronic Modules - Headlamp	Lead [7439-92-1]
Electronic Modules - Power Decklid/Liftgate (PLG)	Lead [7439-92-1]
Electronic Modules - Seat Control	Lead [7439-92-1]
Electronic Modules - Suspension	Lead [7439-92-1]
Electronic Modules - SYNC	4,4'-Isopropylidenediphenol [80-05-7]
	Lead [7439-92-1]
Engine Water Pumps	Lead [7439-92-1]
Evaporator and Blower	Lead [7439-92-1]
Assemby (HVAC Module)	
Fascia Grille - Radiator	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Fixed Glass	Lead [7439-92-1]
Fuel Door	Lead [7439-92-1]
GOR and Radiator Support	Lead [7439-92-1]
Headlamp / Side Marker	Diboron-trioxide [1303-86-2]
	Lead [7439-92-1]
	TBBA [79-94-7]
Headliner / Sunvisor	Lead [7439-92-1]
I/S Mirror	Lead [7439-92-1]
Instrument Cluster	Lead [7439-92-1]
	TBBA [79-94-7]
Interior Lighting	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
Latches - Hood, Decklid and Liftgate Latches	Lead [7439-92-1]
<u> </u>	TBBA [79-94-7]
Latches - Side Door/Latch Mini Module	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Lead [7439-92-1]
Locks	Lead [7439-92-1]
Luggage and Interior Cargo Management/Covers	Lead [7439-92-1]
Mirrors	Decamethylcyclopentasiloxane [541-02-6]
	Lead [7439-92-1]
Park Assist	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Lead [7439-92-1]
Pedestrian Alert System (PAS)	Lead [7439-92-1]
	N,N-Dimethylacetamide [127-19-5]
Plastic Bumpers and Fascias	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
Powertrain Control Module (PCM/EEC/ ECM)	Lead [7439-92-1]
Sealing - Glass Runs and Belt Moldings	Lead [7439-92-1]
	Melamine [108-78-1]
Seat Belts (Front and Rear)	Lead [7439-92-1]
Seats - Structures	Lead [7439-92-1]

	Sodium borate, decahydrate [1303-96-4]
Shock Absorbers	Lead [7439-92-1]
	Nonylphenol [25154-52-3]
Side and Rear Vision (BLIS)	Lead [7439-92-1]
	TBBA [79-94-7]
Smart Junction Box & Body	Diboron-trioxide [1303-86-2]
Control Module (SPDJB)	
	Lead [7439-92-1]
Speakers / Tweeters	6,6'-Di-tert-butyl-2,2'-methylenedi-p-cresol [119-47-1]
	Imidazolidine-2-thione [96-45-7]
Steering Column	Lead [7439-92-1]
Steering Gear and Linkage	Lead [7439-92-1]
Steering Wheel, Drive Air Bag	Dicyclohexyl-phthalate [84-61-7]
	Lead [7439-92-1]
Switches - General Use	Lead [7439-92-1]
Switches - Headlamp.	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one
Window & Door	[71868-10-5] Lead [7439-92-1]
Switches - Steering Column	Diboron-trioxide [1303-86-2]
Switches - Steering Column	TBBA [79-94-7]
Taillamp / Redundant	Lead [7439-92-1]
Temperature Sensors -	•
Climate	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one [71868-10-5]
	Lead [7439-92-1]
TPMS	Decamethylcyclopentasiloxane [541-02-6]
Transmission (Auto) - Oil Pumps	Lead [7439-92-1]
Transmission (Auto) - Park Locking Mechanism	Lead [7439-92-1]
Wiper Assembly (Rear, Front) & Washer System	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	C,C'-azodi(formamide) [123-77-3]
	Imidazolidine-2-thione [96-45-7]
	Lead [7439-92-1]
xEV - DCDC	Lead [7439-92-1]
xEV - eDrive	Lead [7439-92-1]
	N,N-Dimethylacetamide [127-19-5]
xEV - Traction Battery	Lead [7439-92-1]
Charging	